Fall 2012 Levee Maintenance Deficiency Summary Report Overall LMA & Unit Ratings, including USACE Erosion Survey

Sacramento River Basin

RD1601 Reclamation District No. 1601 Twitchell	Overall LMA Rating	Total LMA Miles						
	A	2.47						
Rated Item		Maintena	nce Deficiancy		Enforc	ement		& System scence
Nateu item	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
No Items								
LMA Totals:	0.00	0.00	0.00	0.00%				

LMA District Cover Sheet

Fall 2012 Levee Inspection Results

Reclamation District No. 1601 Twitchell

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)		
* Overall LMA Rating (Fall Only)			A			
	** Non-receipt of Su	ımmer or Winter Inspe	ection Reports may effec	ct overall annual rating		
* SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall. FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified						
within the attached u	nit inspection reports.					
comments						

Unit Cover Sheet

Fall 2012 Levee Inspection Results

Reclamation District No. 1601 Twitchell

Waterway	Bank	Unit Miles
Unit No. 01 Threemile Slough	Left	2.47

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			Α	
Date of Inspection	04/03/2012 - 04/03/2012		10/16/2012 - 10/16/2012	
DWR Inspector	Richard Willoughby		Richard Willoughby	
Accompanied By				

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

http://cdec.water.ca.gov/lma.html

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

Levee Inspection Report By Mile - Fall 2012

Reclamation District No. 1601 Twitchell

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Threemile Slough	Left	2.47	10/16/2012 10/16/2012	Richard Willoughby

LMR	Levee	Mile	Category	Item	Location	Action/Comment	GPS Latitud	e/Longitude	Issue No.
No.	Start	End	Calegory	пеш	tion	Action/Comment	Start	End	Photo
1	0.00	0.00	Earthen Levee	Operations & Maintenance Manuals	CR A		o o DWR ID: DWR_RE	o 0 01601_01_s _ 2012	J
2	0.00	0.00	Earthen Levee	Emergency Supplies & Equipment	CR A		o o DWR ID: DWR_RE	o o 01601_01_s _ 2012	7
3	0.00	0.00	Earthen Levee	Flood Preparedness & Training	CR A		o o DWR ID: DWR_RI	o o 01601_01_s _ 2012	O
4	0.00	2.47	Earthen Levee	Vegetation	WS A	, 3	o o DWR ID: DWR_RD	o 01601_01_f _ 2012_	Y
5	0.10	1.31	Earthen Levee	Crown Surface / Depressions / Rutting	CR A/V	V C2 : Repair depressions or ruts in the crown or slope.	38.120883 ° -121.682775 ° -		Υ

Levee Inspection Report By Mile - Fall 2012

Reclamation District No. 1601 Twitchell

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Threemile Slough	Left	2.47	10/16/2012 10/16/2012	Richard Willoughby

Levee Mile Report Line	4
Start Levee Mile	0.00
End Levee Mile	2.47
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Looking south at typical v	view of levee.



Levee Mile Report Line	5			
Start Levee Mile	0.10			
End Levee Mile	1.31			
Location	Crown			
Category	Earthen Levee			
Item Crown Surface / Depressions / Rutting				
Looking north at holes on levee crown.				

richard_f_20121012_829.jpg

Levee Mile Report Line	5
Start Levee Mile	0.10
End Levee Mile	1.31
Location	Crown
Category	Earthen Levee
Item	Crown Surface / Depressions / Rutting
Looking south at crown s	urface rutting.

richard_f_20121012_830.jpg







** Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiancy Ob : Design & System Obsolescence En : Enforcement

Levee Inspection Report By Mile - Fall 2012

Reclamation District No. 1601 Twitchell

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Threemile Slough	Left	2.47	10/16/2012 10/16/2012	Richard Willoughby

Levee Mile Report Line	5			
Start Levee Mile	0.10			
End Levee Mile	1.31			
Location	Crown			
Category	Earthen Levee			
Item	Crown Surface / Depressions / Rutting			
Looking southwest at re-grade crown roadway.				
richard_f_20121018_895.JPG				

